

Automatic Control Systems

Sheet (01)

Name:

Sec No

1. Find the inverse Laplace transform for each of the following functions

$$F(s) = \frac{2s + 12}{s^2 + 2s + 5}$$

$$F(s) = \frac{s + 1}{s(s^2 + s + 1)}$$

$$F(s) = \frac{6s + 3}{s^2}$$

$$F(s) = \frac{5s + 2}{(s + 1)(s + 2)^2}$$

2. Solve the following differential equations

$$2\ddot{x} + 7\dot{x} + 3x = 0 \quad x(0) = 3, \quad \dot{x}(0) = 0$$

$$\ddot{x}(t) + 2\dot{x}(t) + x(t) = 3te^{-t} \quad x(0) = 4, \quad \dot{x}(0) = 2$$

$$\dot{x} + ax = A \sin \omega t \quad x(0) = b$$

$$\ddot{x} + 2\zeta\omega_n\dot{x} + \omega_n^2x = 0 \quad x(0) = a, \quad \dot{x}(0) = b$$

$$\ddot{y}(t) + 2\dot{y}(t) + 5y(t) = e^{-t}\sin t \quad y(0) = 0 \quad \dot{y}(0) = 1$$

$$\ddot{y}(t) + 2\dot{y}(t) + y(t) = t \quad y(0) = -3 \quad y(1) = -1$$