

Microprocessor

CALL — INCLUDE

To call a procedure

1. Write down your procedure as below

```
print proc
; print a line of sterisk
        mov cx,40d
        mov ah,02h
        mov dl,'*'
again:   int 21h
        loop again
        ret
print endp
```

2. Write down your main code

```
.model small
.stack 64
.data
.code
main proc far
        mov ax,@data
        mov ds,ax
```

```
        call print
        mov ah,4ch
        int 21h
main endp

        include d:\pstar.asm

end main
```